

4-Takt Ringliste

| Wössner-No | Ø | 1st.Groove | 2nd. Groove | Oil-Groove | | Ringendgap |
|------------|-------|------------|-------------|------------|--|------------|
| 530XKS | 53 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 535XKS | 53,5 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 540XKS | 54 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 545XKS | 54,5 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 550XKS | 55 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 560XKS | 56 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 570XKS | 57 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 580XKS | 58 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 590XKS | 59 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 595XKS | 59,5 | 1x2.4 | 0.8x2.5 | 2x2.4 | | 0,1-0,25 |
| 600XGS | 60 | 1x2.65 | 1x2.7 | 2x2.7 | | 0,1-0,25 |
| 605XGS | 60,5 | 1x2.65 | 1x2.7 | 2x2.7 | | 0,1-0,25 |
| 610XKS | 61 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 615XKS | 61,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 620XKS | 62 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 625XKS | 62,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 630XKS | 63 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 635XKS | 63,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 640XKS | 64 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 645XKS | 64,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 650XGS | 65 | 1x2.65 | 1x2.7 | 2x2.7 | | 0,1-0,25 |
| 655XGS | 65,5 | 1x2.65 | 1x2.7 | 2x2.7 | | 0,1-0,25 |
| 660XKS | 66 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 665XKS | 66,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 670XKS | 67 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 675XKS | 67,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 680XKS | 68 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 685XKS | 68,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 690XKS | 69 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 695XKS | 69,5 | 1x2.6 | 0.8x2.7 | 2x2.7 | | 0,1-0,25 |
| 700XKS | 70 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,1-0,25 |
| 705XKS | 70,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,1-0,25 |
| 710XDS | 71 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 715XDS | 71,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 720XDS | 72 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 725XDS | 72,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 730XDS | 73 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 735XDS | 73,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 740XDS | 74 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 745XDS | 74,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 750XDS | 75 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 755XDS | 75,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 760XDS | 76 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 760XMS | 76 | 0.8x2.65 | 0.8x3.1 | 2x2.7 | | 0,15-0,25 |
| 765XDS | 76,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 770XKS | 77 | 1x3.1 | 0.8x3.1 | 2x2.7 | | 0,15-0,25 |
| 770XDS | 77 | | 1.2x3.5 | | | 0,15-0,30 |
| 775XDS | 77,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 780XMS | 78 | 0.8x2.65 | 0.8x3.1 | 2x2.7 | | 0,15-0,25 |
| 780XDS | 78 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 785XDS | 78,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 787XDS | 78,75 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 790XMS | 79 | 0.8x2.65 | 0.8x3.1 | 2x2.7 | | 0,15-0,25 |
| 790XDS | 79 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |

4-Takt Ringliste

| | | | | | | |
|---------|-------|----------|---------|---------|--|-----------|
| 795XDS | 79,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,15-0,30 |
| 800XDS | 80 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,20-0,35 |
| 805XDS | 80,5 | 1x3.1 | 1.2x3.5 | 2x2.7 | | 0,20-0,35 |
| 810XSY | 81 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 815XSY | 81,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 820XSY | 82 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 825XSY | 82,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 827XSY | 82,75 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 830XSY | 83 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 835XSY | 83,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 840XSY | 84 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 845XSY | 84,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 850XSY | 85 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 855XSY | 85,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 860XSY | 86 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 865XSY | 86,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 870XSY | 87 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 875XSY | 87,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 880XSY | 88 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 885XSY | 88,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 890XSY | 89 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 892XSY | 89,25 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 895XSY | 89,5 | 1x3.1 | 1.2x3.5 | 2.5x2.9 | | 0,20-0,35 |
| 900XSY | 90 | 1x3.3 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 905XSY | 90,5 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 910XSY | 91 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 910XSU | 91 | 1.2x3.7 | 1.5x3.7 | 2.5x2.9 | | 0,20-0,35 |
| 912XSU | 91,2 | 1.2x3.7 | 1.5x3.7 | 2.5x2.9 | | 0,20-0,35 |
| 915XSY | 91,5 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 920XSY | 92 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 920XSU | 92 | 1.2x3.7 | 1.5x3.7 | 2.5x2.9 | | 0,20-0,35 |
| 925XSY | 92,5 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 930XSY | 93 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 935XSY | 93,5 | 1x3.5 | 1.2x3.8 | 2.5x2.9 | | 0,20-0,35 |
| 940XSY | 94 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,20-0,35 |
| 945XSY | 94,5 | 1x3.5 | 1.2x4.2 | 2.5x2.9 | | 0,20-0,35 |
| 950XSY | 95 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 955XSY | 95,5 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 960XSY | 96 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 965XSY | 96,5 | 1x3.5 | 1.2x4.0 | 2.8x2.9 | | 0,15-0,30 |
| 970XSY | 97 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 975XSY | 97,5 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 980XSY | 98 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 990XSY | 99 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,15-0,30 |
| 995XSY | 99,5 | 1x3.5 | 1.2x4.2 | 2.5x2.9 | | 0,20-0,35 |
| 1000XSY | 100 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,20-0,35 |
| 1010XSY | 101 | 1x3.5 | 1.2x4.0 | 2.5x2.9 | | 0,20-0,40 |
| 1016XSU | 101,6 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1020XSU | 102 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1030XSU | 103 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1035XSU | 103,5 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1040XSU | 104 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1045XSU | 104,5 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1050XSU | 105 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1055XSU | 105,5 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |
| 1060XSU | 106 | 1.2x3.65 | 1.5x4.2 | 2.5x2.9 | | 0,20-0,40 |